



**National
Aeronautical
Laboratory**

Documentation Sheet

Document Classification

RESTRICTED

Title : REPORT ON THE CRACK IN THE BOTTOM
WING ROOT FITTING OF KIRAN AIRCRAFT

Document No.

PD MT 8905

Date of issue: Feb 1989

Author(s) : A.C.Raghuram, S.Radhakrishnan and
R.V.Krishnan

Contents

Pages - 2

Figures - 6

Division : Materials Science Division

No. of copies: 13

External participation : --

NAL Project No.

MT-1-167, MT-9-001

Sponsor : --

Sponsor's Project No.

Approval : Dr A.C.Raghuram

Remarks :

Keywords : Stress Corrosion, Wing Root Fitting
Kiran Aircraft

Abstract : The crack in the bottom wing root fitting of a Kiran aircraft was analysed and found to be due to stress corrosion cracking.